



« [1996 Town Car/Crown Victoria/Grand Marquis Table of Contents](#) »

«[Group 15: AUDIO SYSTEMS](#)»

«[Section 15-04: Phone, Mobile](#)»

«[DIAGNOSIS AND TESTING](#)»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST A: PHONE DOES NOT POWER UP

A6 TEST PHONE TRANSCEIVER

- Replace mobile telephone transceiver with a known good one.
- **Does system power up?**

Yes

SERVICE mobile telephone transceiver and RETEST.

No

SERVICE phone wiring. REFER to [«Section 18-01»](#).
