



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST C: REDUCED SOUND OR NO SOUND THROUGH AUDIO SPEAKER

C1 CHECK CONTINUITY OF CIRCUIT 725 (PK)

- Measure the resistance between Pin C2-10 of mobile phone transceiver connection and Pin C4-12 of rear chassis unit connector.

- **Is resistance less than 5 ohms?**

Yes

GO to «C2».

No

SERVICE wiring. REFER to «Section 18-01».
