



« [1996 Town Car/Crown Victoria/Grand Marquis Table of Contents](#) »

«[Group 15: AUDIO SYSTEMS](#)»

«[Section 15-04: Phone, Mobile](#)»

«[DIAGNOSIS AND TESTING](#)»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST C: REDUCED SOUND OR NO SOUND THROUGH AUDIO SPEAKER

C4 CHECK PHONE TRANSCEIVER

- Substitute mobile telephone transceiver with a known good one and retest.
- **Does system work properly?**

Yes

REPLACE old mobile telephone transceiver.

No

REPLACE rear chassis unit. RETEST system. REFER to [«Section 15-01»](#).
