



« [1996 Town Car/Crown Victoria/Grand Marquis Table of Contents](#) »

«[Group 15: AUDIO SYSTEMS](#)»

«[Section 15-04: Phone, Mobile](#)»

«[DIAGNOSIS AND TESTING](#)»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST D: RADIO DISPLAYS PHONE CONSTANTLY

D2 CHECK FRONT CONTROL UNIT

- Disconnect phone transceiver connector C2 and front control unit connector.
- Measure resistance between front control unit connector Pin C1-4, Circuit 723 (GY/R) and a known good ground.
- **Is the resistance greater than 1 M ohms?**

Yes

REPLACE front control unit. RETEST system. REFER to «[Section 15-01](#)».

No

SERVICE wiring. REFER to «[Section 18-01](#)».
