



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

---

## Pinpoint Tests

### PINPOINT TEST F: POOR RECEPTION, STATIC ON CALLS, FREQUENT DROP OF CALLS

---

#### F4 CHECK INSIDE BASE CONNECTOR

---

- Check connector on inside base of mobile telephone antenna.
- **Is connector on inside base of mobile telephone antenna loose?**

#### Yes

Note: Antenna bases are designed to be mounted only once. If a base is damaged or removed, or the mounting adhesive has been damaged, the base must be scrapped. Inside and outside bases must match up extremely close to pass the test when replacing bases. INSTALL new inside base and RETEST.

#### No

GO to «F5».

---