



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST F: POOR RECEPTION, STATIC ON CALLS, FREQUENT DROP OF CALLS

F6 REPLACE ANTENNA CABLE

- Replace multi-function control antenna cable.
- Retest.
- **Does the system pass?**

Yes

System OK.

No

REPLACE both mobile telephone antenna bases.
