



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents »
«Group 15: AUDIO SYSTEMS»
«Section 15-04: Phone, Mobile»
«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST G: MICROPHONE NOT OPERATING PROPERLY

G2 CHECK DIGITAL VOICE CALLER WIRING CONTINUITY

- Measure resistance between Circuit 728 (W/O) at mobile telephone microphone and Pin C1-7 at connection to mobile telephone transceiver.
- **Is resistance less than 5 ohms?**

Yes

REPLACE mobile telephone transceiver and RETEST.

No

SERVICE wiring. REFER to «[Section 18-01](#)».
