



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»
«Group 15: AUDIO SYSTEMS»
«Section 15-04: Phone, Mobile»
«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST J: CANNOT ENTER PROGRAMMING MODE

J1 VERIFY SECURITY CODE

- Make sure correct entry sequence is used.
- Make sure the entry sequence is input fast enough.
- Verify Security Code. Refer to Step 2 in «[Programming](#)»
- **Has programming mode been entered?**

Yes

System OK.

No

REPLACE mobile telephone transceiver. REPROGRAM system.
