



« [1996 Town Car/Crown Victoria/Grand Marquis Table of Contents](#) »

«[Group 15: AUDIO SYSTEMS](#)»

«[Section 15-04: Phone, Mobile](#)»

«[DIAGNOSIS AND TESTING](#)»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST B: RADIO DISPLAY DOES NOT DISPLAY PHONE

B3 CHECK PHONE TRANSCEIVER ACTIVE

- Short front control unit connector Pin C1-4, Circuit 723 (GY/R) and a known good ground.
- **Does front control unit display "PHONE"?**

Yes

REPLACE mobile telephone transceiver RETEST system.

No

REPLACE front control unit. RETEST system. Refer to [«Section 15-01»](#).
