



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST F: POOR RECEPTION, STATIC ON CALLS, FREQUENT DROP OF CALLS

F5 SUBSTITUTE TRANSCEIVER

- Substitute a known goodmobile telephone transceiver.
- Retest
- **Does the system pass?**

Yes

REPLACEmobile telephone transceiver.

No

GO to [«F6»](#).
