



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST H: NO SVC DISPLAY STAYS ON

H4 MEASURE RESISTANCE

- Disconnect multi-function control antenna cable from mobile telephone transceiver.
- Using an ohmmeter, measure resistance between center conductor and outer shield.
- **Is the resistance approximately 0.3 ohm?**

Yes

GO to **«H5»**.

No

Replacemulti-function control antenna cable.
