



« [1996 Town Car/Crown Victoria/Grand Marquis Table of Contents](#) »

«[Group 15: AUDIO SYSTEMS](#)»

«[Section 15-04: Phone, Mobile](#)»

«[DIAGNOSIS AND TESTING](#)»

Print Diagnostic Routine

---

## Pinpoint Tests

### PINPOINT TEST K: PHONE VOICE ACTIVATED FUNCTIONS DO NOT OPERATE

---

#### K1 CHECK VOICE ACTIVATION PROGRAMMING

---

- Reprogram voice activated functions with vehicle closed and engine not running. Refer to complete directions in the Cellular Phone Operator's Guide.

- **Was programming successful?**

**Yes**

System operating properly.

**No**

CHECK hands-free operation. REFER to «[Pinpoint Test E](#)».

---