



« [1996 Town Car/Crown Victoria/Grand Marquis Table of Contents](#) »

« [Group 15: AUDIO SYSTEMS](#) »

« [Section 15-04: Phone, Mobile](#) »

« [DIAGNOSIS AND TESTING](#) »

Print Diagnostic Routine

---

## Pinpoint Tests

### PINPOINT TEST C: REDUCED SOUND OR NO SOUND THROUGH AUDIO SPEAKER

---

#### C2 CHECK FOR SHORT ON CIRCUIT 725 (PK)

---

- Measure resistance between Circuit 725 (PK) and a known good ground.
- Is resistance less than 1 K ohms?

**Yes**

SERVICE wiring. REFER to [«Section 18-01»](#).

**No**

GO to [«C3»](#).

---