



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST C: REDUCED SOUND OR NO SOUND THROUGH AUDIO SPEAKER

C3 CHECK CONTINUITY OF CIRCUIT 724 (LB/Y)

- Measure resistance between Pin C2-11 of connection to mobile telephone transceiver and Pin C4-11 of connection to rear chassis unit connector.

- **Is resistance less than 5 ohms?**

Yes

GO to «C4».

No

SERVICE wiring. REFER to «Section 18-01».
