



« 1996 Town Car/Crown Victoria/Grand Marquis Table of Contents»

«Group 15: AUDIO SYSTEMS»

«Section 15-04: Phone, Mobile»

«DIAGNOSIS AND TESTING»

Print Diagnostic Routine

Pinpoint Tests

PINPOINT TEST C: REDUCED SOUND OR NO SOUND THROUGH AUDIO SPEAKER

- ➔ C1: CHECK CONTINUITY OF CIRCUIT 725 (PK)
 - ➔ C2: CHECK FOR SHORT ON CIRCUIT 725 (PK)
 - ➔ C3: CHECK CONTINUITY OF CIRCUIT 724 (LB/Y)
 - ➔ C4: CHECK PHONE TRANSCEIVER
-